


CABLE CRYSTAL LIGHT BOX INSTALLATION INSTRUCTIONS

STEP 1 - TAKE THE POWER SUPPLY AND STRIP THE ENDS OF THE CABLE



STEP 2 - TEST POWER SUPPLY BY TOUCHING STRIPPED ENDS TO CABLE - ONE END TO EACH CABLE




NOTE: IF CRYSTAL LIGHT BOX DOESN'T LIGHT UP, SWITCH THE ENDS TO THE OTHER SIDE

STEP 3 - REMOVE TOP PORTION OF FIXING BY TURNING COUNTER CLOCKWISE



STEP 4 - REMOVE SPRING & CABLE LOCK FROM THE FIXING BARREL. LOOSEN HEX NUTS ON CABLE LOCK WITH HEX KEY (SOLD SEPARATELY)



STEP 5 - RUN CABLE THROUGH CENTER OF FIXING, SPRING & INTO THE CABLE LOCK. TIGHTEN HEX NUTS WITH HEX KEY



STEP 6 - SCREW ASSEMBLED UNIT BACK ONTO FIXING BY TURNING CLOCKWISE



ASSEMBLED UNIT WILL LOOK LIKE THIS




STEP 7 - TURN FIXING OVER & REMOVE NUT INSIDE THE BASE




NUT

STEP 8 - WRAP STRIPPED END OF CABLE FROM THE POWER SUPPLY AROUND THE SCREW INSIDE THE BASE



SCREW

STEP 9 - RE-ATTACH THE NUT, CAREFUL TO MAKE SURE THE CABLE STAYS WRAPPED AROUND THE SCREW MAKING CONTACT WITH IT.



REPEAT STEPS 3-9 FOR SECOND SIDE

COMPLETED UNIT WILL LOOK LIKE THIS & IS READY TO BE MOUNTED.



ONCE BOTH SIDES ARE MOUNTED, POWER SUPPLY CAN BE PLUGGED INTO OUTLET

